



# Logger Patches

Every extension is fitted with a handset adapter (logger patch), which in turn is connected to a recording channel. Because audio is picked up from the earpiece as well as from the microphone, audio level differences may occur. This is a limitation of the pickup method not of the recorder.

